

Mercedes-Benz USA, LLC

A Daimler Company

SENT VIA CERTIFIED U.S. MAIL

January 7, 2010

National Highway Traffic Safety Administration Attention: George Person, Chief, Recall Analysis Division 1200 New Jersey Avenue Seventh, S.E. Washington, D.C. 20590

Dear Mr. Person:

Please find the Quarterly Report of Defect Notification Campaigns for the quarter ending December 31, 2009.

Should you have any questions, please do not hesitate to contact me at 201-573-2622.

Sincerely,

R-Thomas Brunner

Department Manager, Product Compliance, Analysis, Safety & Emissions

Associate General Counsel & Assistant Secretary

Enclosure

MANUFACTURER									QUARTER ENDING
MERCEDES-BENZ USA, LLC.									December 31, 2009
			MOT	OR VEHICLE SAFET	TY DEFECT REPORT	Ī			
			QUARTERLY	REPORT DEFECT	NOTIFICATION CAN	IPAIGNS			
MBUSA REFERENCE NUMBER		2008050004	2008070001	2008080004	2003040005	2008120011	2009010002	2009030001	2009030003
ABBREVIATED DESCRIPTION		ML, GL	ML,GL,SLK,C,CLK	CL,S,SL,	ML	ML, GL, R	S	s	ML
		TRAILER	E,CL, CLS,S,SL,R,G	ABC	POWER	POWER	ABC	DOOR	POWER
į		HITCH	SCN CODING	SENSOR	STEERING HOSE	STEERING RACK	STRUT	LOCK	LIFT GATE
REPORT NO.	(573.6)	6	6	5	5	4	3	3	3
CAMPAIGN NO.	b(1)	08V-242	08V-303	08V-405	*08V-465	08V-682	08V-608	09V-081	09V-076
DATE STARTED	b(2)	6/4/2008	7/25/2008	9/12/2008	10/31/2008	1/24/2009	2/4/2009	3/27/2009	4/17/2009
NOTIFICATION ENDED	b(2)								
NUMBER OF VEHICLES									
INVOLVED IN CAMPAIGN: b(3)		52120	409	4579	125981	577	1524	54	17901
\ REPAIRED: b(4i)		40650	343	4186	60574	439	1250	37	14323
INSPECTED									
REPAIR NOT NEEDED: b(4ii)		0	0	0	0	0	0	0	0
CORRECTIVE MEASURES									
COMPLETED: b(5)		40650	343	4186	60574	439	1250	37	14323
UNREACHABLE	b(6)	0	0	0	0	0	0	0	0
STOLEN		0	0	0	0	0	0	0	0
SCRAPPED		0	0	0	0	0	0	.0	0
SOLD-OWNER UNKNOWN		0	0	0	0	0	0	_0	
OUT OF U.S.		0	0	0	0	0	0	0	0
MOVED-NO ADDRESS		0	0	0	0	0	0		0
UNCLAIMED LETTER		0	0	0	0	0	0	0	0
UNCOOPERATIVE		0	0	0	0	0	0	0	0
COMPLETION PERCENT		77.99%	83.86%	91.42%	48.08%	76.08%	82.02%	68.52%	80.01%

^{*} Originally launched in 2003 as NHTSA Recall # 03V-121